

ZA180A Zero air

Aria zero

Numero dell'articolo: 30-1660 (230v) - UK | 30-1670 (230v) - EU | 30-1680 (110v) - US




Descrizione

Generando aria zero per il gas del rilevatore nelle applicazioni GC, il generatore ZA180A rimuove tutti gli idrocarburi da una fonte di aria compressa prima che entrino nella strumentazione, assicurando i risultati più ordinati dal rilevatore.



Generator Details

- **Tipo di gas:** Aria
- **Compressore integrato:** Sì



Caratteristiche principali

- Produce zero air a <math><0.1\text{ ppm}</math> di contenuto
- Esegue 24 ore su 24, 7 giorni su 7, se necessario
- Un generatore può fornire più strumenti
- Poche parti in movimento significano poca manutenzione e garantiscono una lunga durata del generatore
- Richiede una configurazione minima
- Garanzia on-site completa di 12 mesi

Specifiche tecniche

	ZA180A Aria zero
Tipo di gas	Aria
Flusso massimo di gas:	18L/min
Contenuto di idrocarburi:	0.1ppm
Purezza massima:	0.1ppm THC
Tempo di avvio:	40 Minutes
Consumo di energia:	770 Watts
Voltaggio:	110 / 230 ± 10% VAC
Frequenza:	60 Hz
Corrente:	2/4 Amps
Temperatura operativa massima:	30°C / 86°F
Accreditamenti:	CE
Dimensioni (AxLxP) in mm	880 x 430 x 410 mm
Dimensioni (AxLxP) in pollici	34,6 x 16,9 x 16,1 inches
Peso del generatore	64kg / 140,8lbs

[PEAK Protected]TM

Peak Scientific gas generators define the benchmark in reliability, convenience and performance in laboratories around the world, and come backed with a 12 month warranty. Beyond this period however you can ensure that your investment continues to be **[Protected]** by our comprehensive generator care cover.

Our world-class aftercare support packages deliver a program of scheduled preventative maintenance whilst giving you the reassurance of instant access to worldwide technical support and priority on-site response in the untimely event of a breakdown.

- For ordering parts visit: www.peakscientific.com/ordering/
- For service plans visit: www.peakscientific.com/service/service-plans/

Peak Scientific UK
Tel: +44 (0)141 812 8100
Fax: +44 (0)141 812 8200

Peak Scientific North America
Tel: +1-800-767-6532
Fax: +1-978-608-9503

Peak Scientific China
Tel: +86 21 5079 1190
Fax: +86 21 5079 1191
For a full list of our worldwide office locations, please visit:
Web: www.peakscientific.com
Email: discover@peakscientific.com

Peak Scientific's Quality Management System conforms to: ISO:9001

